

Notice of temporary overnight closures A38 carriageways in both directions from Hilliard's Cross to Swinfen Interchange and Streethay southbound exit slip

HS2-BBV-26-2249

Location

A38 southbound exit slip: Full closure of the exit slip road

A38 northbound: Cappers Lane to Hilliard's Cross

A38 southbound: Hilliard's Cross to Swinfen Interchange

Duration

A38 southbound exit slip: Five overnight closures **Sunday 23 August to Thursday 27 August 2026 9pm to 6am** (inclusive)

A38 northbound: One overnight closure **Tuesday 1 September 2026 9pm to 6am**

A38 southbound: One overnight closure **Wednesday 2 September 2026 9pm to 6am**

What we are doing

We will be undertaking work on the off slip permanent barrier, installing signage and pavement investigation works. **These works are subject to consent.**

What to expect

Some low-level noise may be generated in the area during working hours. A signed diversion route will be in place.

We are committed to keeping you informed about work on HS2. This includes ensuring you know what to expect and when to expect it, as well as how we can help you. Should you have any questions or concerns about our works you can contact us by:



Freephone **08081 434 434**



Minicom **08081 456 472**



Email **HS2enquiries@hs2.org.uk**



Writing to **FREEPOST
HS2 Community Engagement**



Website **www.hs2.org.uk**

Keep up to date with what is happening in your local area at
**[www.hs2.org.uk/in-your-area/
in-your-area-map/](http://www.hs2.org.uk/in-your-area/in-your-area-map/)**

Where we will be working


We will be working on the A38 in Lichfield between Swinfen Interchange and Hilliard's Cross.

Please see the maps and diversion routes below for the northbound and southbound carriageways and southbound exit slip

Please plan ahead and allow extra time for your journeys during the closure.

A38 northbound diversion route:

- Take the exit for Cappers Lane A5192 and turn left onto Cappers Lane
- Continue straight ahead at the next roundabout to Trent Valley roundabout
- Take the 3rd exit onto Eastern Avenue and continue ahead
- At the traffic lights, turn left on to A51 Stafford Road
- At the roundabout, take the 2nd exit onto A515 Tewnals Lane
- Turn right onto Wood End Lane and continue straight to rejoin the A38 northbound carriageway



— Closure
- - - Diversion


Date: 10/02/2025

Scale: 1:40,000

A38 Southbound diversion_240423035242-BBVGIS-3422 WM_BO

A38 southbound diversion route:

- Leave the A38 at Hilliard's Cross and turn left onto Wood End Lane
- Continue straight ahead, then turn left onto Tewnals Lane to join the A515
- At the roundabout, take the 1st exit towards the A51 Lichfield Western Bypass/Stafford Road
- Continue straight over the roundabout onto The Friary
- At the next roundabout, take the 3rd exit onto Sainte Foy Avenue.
- Proceed straight over the next two roundabouts then take the 1st exit onto the A461 Lichfield Southern Bypass
- Continue to the traffic lights and turn right onto the A5206 London Road
- Follow the A5206 back to Swinfen Interchange and rejoin the A38



— Closure
- - - Diversion


Date: 22/01/2026

Scale: 1:45,000

A38 Southbound Closure Diversion Route INC000004936705-02 WS TR

A38 southbound exit slip road closure diversion route

- Southbound traffic will continue on the A38 to Swinfen Interchange
- Take the 4th exit on the roundabout to join the A38 northbound
- Take the exit for Cappers Lane A5192 and turn left onto Cappers Lane
- Continue straight ahead at the next roundabout to Trent Valley roundabout where the diversion ends



Please contact us if you'd like a free copy of this document in large print, Braille, audio or 'easy read' format. You can also contact us for help and information in a different language.

Holding us to account

If you are unhappy for any reason, you can make a complaint by contacting our HS2 Helpdesk team. For more information, visit: www.hs2.org.uk/how-to-complain

We have an independent Residents' and Construction Commissioner who helps settle disputes and monitors the way in which we manage and respond to complaints about construction.

For more information visit: www.hs2.org.uk/independent-commissioner